

FORM 600 AMP-TRAP FUSE
MELTING TIME CURRENT DATA
70-2000 AMPS

CAT. NO. A2Y(70-600)-3, 4, 5

A5Y(70-600)-3

A6Y(100-2000)-3, 4, 5, 21, 58, 3G

250VAC/500VDC

500VAC/500VDC

600VAC/500VDC

FERRAZ SHAWMUT
NEWBURYPORT, MA 01950

26122

CONTROL NO. : 186
REV G
1-19-01

