

CABLE PROTECTOR AMP-TRAP FUSE

CL-14

A083C1D0R0-60E


60E 8.3KV

MINIMUM MELTING TIME CURRENT CURVE

FERRAZ SHAWMUT  
NEWBURYPORT, MA 01950

720468

CURRENT IN AMPERES X10



CONTROL No: 1190  
FOLDER NO.: 14A  
REV A  
2-13-08