



DECLARATION OF RoHS CONFORMITY

July 15, 2020

Declaration N°: RS000144

Mersen USA EP Corp.
374 Merrimac Street
Newburyport, MA 01950-1998

The following fuse related products listed in the table below in this declaration do not contain any of the below substances above the maximum concentration values identified in Annex II of the RoHS Directive (2011/65/EU) and its amendment (EU) 2015/863,

MPDB Series UL 1953 Open-Style Power Distribution Blocks (see Table 1)

Quantity limit: 0.1 % of weight (1000ppm) of any homogeneous material:

1. Lead (Pb)
2. Mercury (Hg)
3. Hexavalent Chromium (Cr VI)
4. Polybrominated Biphenyls (PBB)
5. Polybrominated Diphenyl Ethers (PBDE)
6. Bis(2-Ethylhexyl) phthalate (DEHP)
7. Benzyl butyl phthalate (BBP)
8. Dibutyl phthalate (DBP)
9. Diisobutyl phthalate (DIBP)

Quantity limit: 0.01 % of weight (100 ppm) of any homogeneous material:

1. Cadmium (Cd)

Timothy B. Haskins
VP of Quality Electrical Protection North America
Electrical Power

MERSEN USA EP Corp.

374 MERRIMAC STREET — NEWBURYPORT, MA 01950
T 978 462 6662 — F 978 462 0181 — info.nby@mersen.com

ep.mersen.com



Table 1

MPDB Series UL 1953 Open-Style Power Distribution Blocks

Compliant					
MPDB62100	MPDB66403	MPDB67253	MPDB67592	MPDB69001	MPDB69170
MPDB62101	MPDB66450	MPDB67400	MPDB67593	MPDB69002	MPDB69171
MPDB62102	MPDB66451	MPDB67401	MPDB67610	MPDB69003	MPDB69172
MPDB62103	MPDB66452	MPDB67402	MPDB67611	MPDB69010	MPDB69173
MPDB62160	MPDB66453	MPDB67403	MPDB67612	MPDB69011	MPDB69180
MPDB62161	MPDB66460	MPDB67410	MPDB67613	MPDB69012	MPDB69181
MPDB62162	MPDB66461	MPDB67411	MPDB67620	MPDB69013	MPDB69182
MPDB62163	MPDB66462	MPDB67412	MPDB67621	MPDB69020	MPDB69183
MPDB62200	MPDB66463	MPDB67413	MPDB67622	MPDB69021	MPDB69191
MPDB62201	MPDB66490	MPDB67420	MPDB67623	MPDB69022	MPDB69210
MPDB62202	MPDB66491	MPDB67421	MPDB67630	MPDB69023	MPDB69211
MPDB62203	MPDB66492	MPDB67422	MPDB67631	MPDB69030	MPDB69212
MPDB62204	MPDB66493	MPDB67423	MPDB67632	MPDB69031	MPDB69213
MPDB63100	MPDB66520	MPDB67430	MPDB67633	MPDB69032	MPDB69230
MPDB63101	MPDB66521	MPDB67431	MPDB67650	MPDB69033	MPDB69231
MPDB63102	MPDB66522	MPDB67432	MPDB67651	MPDB69040	MPDB69232
MPDB63103	MPDB66523	MPDB67433	MPDB67652	MPDB69041	MPDB69233
MPDB63130	MPDB66540	MPDB67450	MPDB67653	MPDB69042	MPDB69270
MPDB63131	MPDB66541	MPDB67451	MPDB67660	MPDB69043	MPDB69271
MPDB63132	MPDB66542	MPDB67452	MPDB67661	MPDB69050	MPDB69272
MPDB63133	MPDB66543	MPDB67453	MPDB67662	MPDB69051	MPDB69273
MPDB63134	MPDB66620	MPDB67460	MPDB67663	MPDB69052	MPDB69280
MPDB63135	MPDB66621	MPDB67461	MPDB67670	MPDB69053	MPDB69281
MPDB63140	MPDB66622	MPDB67462	MPDB67671	MPDB69060	MPDB69282
MPDB63141	MPDB66623	MPDB67463	MPDB67672	MPDB69061	MPDB69283
MPDB63142	MPDB66630	MPDB67480	MPDB67673	MPDB69062	MPDB69310
MPDB63143	MPDB66631	MPDB67481	MPDB68060	MPDB69063	MPDB69311
MPDB63144	MPDB66632	MPDB67482	MPDB68061	MPDB69070	MPDB69312
MPDB63150	MPDB66633	MPDB67483	MPDB68062	MPDB69071	MPDB69313
MPDB63151	MPDB66650	MPDB67490	MPDB68063	MPDB69072	MPDB69331
MPDB63152	MPDB66651	MPDB67491	MPDB68090	MPDB69073	MPDB69341
MPDB63153	MPDB66652	MPDB67492	MPDB68091	MPDB69080	MPDB69350
MPDB63154	MPDB66653	MPDB67493	MPDB68092	MPDB69081	MPDB69351
MPDB63160	MPDB66660	MPDB67510	MPDB68093	MPDB69082	MPDB69352

MERSEN USA EP Corp.

374 MERRIMAC STREET — NEWBURYPORT, MA 01950
 T 978 462 6662 — F 978 462 0181 — info.nby@mersen.com

ep.mersen.com



MPDB63161	MPDB66661	MPDB67511	MPDB68110	MPDB69083	MPDB69353
MPDB63162	MPDB66662	MPDB67512	MPDB68111	MPDB69090	MPDB69510
MPDB63163	MPDB66663	MPDB67513	MPDB68112	MPDB69091	MPDB69511
MPDB63164	MPDB66670	MPDB67520	MPDB68113	MPDB69092	MPDB69512
MPDB63190	MPDB66671	MPDB67521	MPDB68120	MPDB69093	MPDB69513
MPDB63191	MPDB66672	MPDB67522	MPDB68121	MPDB69100	MPDB69521
MPDB63192	MPDB66673	MPDB67523	MPDB68122	MPDB69101	MPDB69561
MPDB63193	MPDB67000	MPDB67530	MPDB68123	MPDB69102	MPDB69600
MPDB66000	MPDB67001	MPDB67531	MPDB68140	MPDB69103	MPDB69601
MPDB66001	MPDB67002	MPDB67532	MPDB68141	MPDB69110	MPDB69602
MPDB66002	MPDB67003	MPDB67533	MPDB68142	MPDB69111	MPDB69603
MPDB66003	MPDB67010	MPDB67540	MPDB68143	MPDB69112	MPDB69640
MPDB66200	MPDB67011	MPDB67541	MPDB68150	MPDB69113	MPDB69641
MPDB66201	MPDB67012	MPDB67542	MPDB68151	MPDB69120	MPDB69642
MPDB66202	MPDB67013	MPDB67543	MPDB68152	MPDB69121	MPDB69643
MPDB66203	MPDB67020	MPDB67550	MPDB68153	MPDB69122	MPDB69650
MPDB66230	MPDB67021	MPDB67551	MPDB68220	MPDB69123	MPDB69651
MPDB66231	MPDB67022	MPDB67552	MPDB68221	MPDB69130	MPDB69652
MPDB66232	MPDB67023	MPDB67553	MPDB68222	MPDB69131	MPDB69653
MPDB66233	MPDB67050	MPDB67560	MPDB68223	MPDB69132	MPDB800011
MPDB66260	MPDB67051	MPDB67561	MPDB68290	MPDB69133	MPDB800031
MPDB66260SS	MPDB67052	MPDB67562	MPDB68291	MPDB69140	MPDB800061
MPDB66261	MPDB67053	MPDB67563	MPDB68292	MPDB69141	MPDB900061
MPDB66261SS	MPDB67110	MPDB67570	MPDB68293	MPDB69142	MPDB900071
MPDB66262	MPDB67111	MPDB67571	MPDB68310	MPDB69143	MPDB900091
MPDB66263	MPDB67112	MPDB67572	MPDB68311	MPDB69150	MPDB900121
MPDB66263SS	MPDB67113	MPDB67573	MPDB68312	MPDB69151	MPDBC6263
MPDB66270	MPDB67220	MPDB67580	MPDB68313	MPDB69152	MPDBC6667
MPDB66271	MPDB67221	MPDB67581	MPDB68320	MPDB69153	MPDBC6869
MPDB66272	MPDB67222	MPDB67582	MPDB68321	MPDB69160	MPDBC692W
MPDB66273	MPDB67223	MPDB67583	MPDB68322	MPDB69161	MPDBE6263
MPDB66400	MPDB67250	MPDB67590	MPDB68323	MPDB69162	MPDBE6667
MPDB66401	MPDB67251	MPDB67591	MPDB69000	MPDB69163	MPDBE6869
MPDB66402	MPDB67252				

MERSEN USA EP Corp.

374 MERRIMAC STREET — NEWBURYPORT, MA 01950
 T 978 462 6662 — F 978 462 0181 — info.nby@mersen.com

ep.mersen.com